
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: <u>7/2/2009</u>
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ✓ Damp ☐ Wet ☐	Supervisor: <u>JAW</u>
Manhole_ID: S05KK1003MH	Test ID: <u>D1032-034025</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Manhole	S05KK1003MH
0			Start of Survey	
0			Water Level	
23.70000076			Abandoned Survey	TOO DIRTY, WILL COME DOWN STREA